

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401459338

Date Received:

11/15/2017

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 2 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000

Name of Operator: BP AMERICA PRODUCTION COMPANY

Address: 380 AIRPORT RD

City: DURANGO State: CO Zip: 81303

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Labowskie, Steve</u>		<u>steve.labowskie@state.co.us</u>
<u>Inspections, All</u>		<u>SanJuanCOGCC@bp.com</u>
<u>Leonard, Mike</u>		<u>mike.leonard@state.co.us</u>
<u>Beebe, Sabre</u>	<u>970-375-7530</u>	<u>Sabre.Beebe@bp.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 685303826

Inspection Date: 09/28/2017

FIR Submit Date: 10/02/2017

FIR Status: _____

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY

Company Number: 10000

Address: 380 AIRPORT RD

City: DURANGO State: CO Zip: 81303

LOCATION - Location ID: 326250

Location Name: THOMAS JACQUEZ GU G-N33N10W Number: 10NENW County: LA PLATA

Qtrqtr: NENW Sec: 10 Twp: 33N Range: 10W Meridian: N

Latitude: 37.122709 Longitude: -107.922202

FACILITY - API Number: 05-067-00 Facility ID: 216116

Facility Name: THOMAS JACQUEZ G Number: 1

Qtrqtr: NENW Sec: 10 Twp: 33N Range: 10W Meridian: N

Latitude: 37.122709 Longitude: -107.922202

CORRECTIVE ACTIONS:

2 CA# 104017

Corrective Action: Install or repair required BMPs to comply with rule 1002.f.

Date: 11/02/2017

Response: CA COMPLETED

Date of Completion: 11/07/2017

BP has removed the sediment that has washed into the secondary containment around the tanks, installed rock

Operator Comment: run downs, cleaned out BMP rock rundowns, re-established berms and diversion ditch around the back of the well pad placing rock check dams in the diversion to reduce velocity of flow through the ditch and prevent future rilling. Drainage has been re-established along the edge of the entrance to pad with rock check dams to slow velocity and prevent future rilling along the side of the road. Please see photos of repairs in attached document.

COGCC Decision: _____

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: On November 7, 2017 BP completed repairs and installation of additional BMP's for stormwater management on this well location please see attached photos of work completed. The sign is on order and a closure FIRR with photos will be submitted upon arrival of the new sign.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: _____

Title: Compliance Specialist

Date: 11/15/2017 7:08:50 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
-------------------------------	---------------------------

401459348	Storm water BMP work completion photos
-----------	--

Total Attach: 1 Files