

Inspection Photos
Location Name: Ridgeview 32-16-1
API: 05-081-07747



Photo 1. Fluid and stained soil in separator berm.



Photo 2. Broken sight glass on separator.

Inspection Photos
Location Name: Ridgeview 32-16-1
API: 05-081-07747



Photo 3. Fluid and stained soil at pump jack motor. No containment.



Photo 4. Fluid on flare pit.