

Inspection Photos
Location Name: Ridgeview 32-16-1
API: 05-081-07747



Photo 1. Fluid and stained soil at pump jack motor. No containment.



Photo 2. Fluid and stained soil at pump jack motor. No containment.

Inspection Photos
Location Name: Ridgeview 32-16-1
API: 05-081-07747



Photo 3. Oil in flare pit.



Photo 4. Oil in flare pit

Inspection Photos
Location Name: Ridgeview 32-16-1
API: 05-081-07747



Photo 5. Fluid in separator berm.



Photo 6. Broken sight glass on separator and fluid in separator berm.