

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/20/2017

Submitted Date:

10/10/2017

Document Number:

690900002

**FIELD INSPECTION FORM**

Loc ID: 440549      Inspector Name: FISCHER, ALEX      On-Site Inspection:       2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10091  
 Name of Operator: BERRY PETROLEUM COMPANY LLC  
 Address: 5201 TRUXTUN AVENUE #100  
 City: BAKERSFIELD      State: CA      Zip: 90339

**Findings:**

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

| Contact Name       | Phone | Email                    | Comment |
|--------------------|-------|--------------------------|---------|
| Hogelin, Thomas G. |       | THogelin@bry.com         |         |
| Armstrong, Jon     |       | jarmstrong@bry.com       |         |
| Hughes, Jim        |       | jimo.hughes@state.co.us  |         |
| Colby, Lou         |       | lou.colby@state.co.us    |         |
| Lujan, Carlos      |       | carlos.lujan@state.co.us |         |
| Ramos, Martha      |       | martha.ramos@state.co.us |         |
| Johnson, Derek S   |       | DJohnson@bry.com         |         |

**Inspected Facilities:**

| Facility ID | Type                          | Status | Status Date | Well Class | API Num | Facility Name             | Insp Status |
|-------------|-------------------------------|--------|-------------|------------|---------|---------------------------|-------------|
| 436375      | CENTRALIZED EP WASTE MGMT FAC | AC     | 02/09/2015  |            | -       | House Log Gulch Tank Farm | AL          |

**General Comment:**

On September 20, 2017 COGCC Staff (Alex Fischer, Margaret Ash, Carlos Lujan, Lou Colby, and Jim Hughes) conducted field inspections of Berry Petroleum's House Log Gulch Tan Farm Centralized E&P Facility ID:436375. Berry Petroleum representatives Tom Hogelin and Derek Johnson were present during the site visit. The purpose of the inspection is that Linn Operating LLC - Operator #10516, have requested a bond release for Surety ID#2017-0034 for the House Log Gulch Tank Farm E&P Waste Facility #436375. The operator has stated that this facility was never built.

The existing Location has been and is currently used as a storage and laydown yard. Equipment noted on site include: pipes, racks, dumpster, and equipment.

It does not appear that the House Log Gulch Tank Farm had been constructed.

**Inspected Facilities**

Facility ID: 436375 Type: CENTRALIZE API Number: - Status: AC Insp. Status: AL

**Environmental**

**Spill/Remediation:**

|                    |   |                  |
|--------------------|---|------------------|
| Comment:           | It appears that the House Log Gulch Centralized E&P Waste Management Facility was never constructed.  |                  |
| Corrective Action: | Per Rule 908.g.(2) submit an eForm 27 providing a statement that the House Log Gulch Centralized E&P Waste Management Facility was never constructed. It is suggested that this Inspection Document Number 690900002 be referenced on the eForm 27.<br><br>Per Rule 1004.c.(4) submit an eForm 4 providing a statement that the House Log Gulch Centralized E&P Waste Management Facility was never constructed. It is suggested that this Inspection Document Number 690900002 be referenced on the eForm 4. | Date: 12/10/2017 |

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

| Comment  | User     | Date       |
|--|----------|------------|
| <p>On September 20, 2017 COGCC Staff (Alex Fischer, Margaret Ash, Carlos Lujan, Lou Colby, and Jim Hughes) conducted field inspections of Berry Petroleum's House Log Gulch Tan Farm Centralized E&amp;P Facility ID:436375. Berry Petroleum representatives Tom Hogelin and Derek Johnson were present during the site visit. The purpose of the inspection is that Linn Operating LLC - Operator #10516, have requested a bond release for Surety ID#2017-0034 for the House Log Gulch Tank Farm E&amp;P Waste Facility #436375. The operator has stated that this facility was never built.</p> <p>The existing Location has been and is currently used as a storage and laydown yard. Equipment noted on site include:<br/>pipes,<br/>racks,<br/>dumpster, and<br/>equipment.</p> <p>It appears that the House Log Gulch Centralized E&amp;P Waste Management Facility was never constructed.</p> <p>Per Rule 908.g.(2) submit an eForm 27 providing a statement that the House Log Gulch Centralized E&amp;P Waste Management Facility was never constructed. It is suggested that this Inspection Document Number 690900002 be referenced on the eForm 27.</p> <p>Per Rule 1004.c.(4) submit an eForm 4 providing a statement that the House Log Gulch Centralized E&amp;P Waste Management Facility was never constructed. It is suggested that this Inspection Document Number 690900002 be referenced on the eForm 4.</p> | fischera | 10/10/2017 |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description  | URL   |
|--------------|--|---|
| 401424834    | INSP Location ID 440549 CE and P Facility ID 436375 20170920 Photo | <a href="#">INSP Location ID 440549 CE and P Facility ID 436375 20170920 Photo.pdf</a>  |
| 401424863    | INSPECTION SUBMITTED   | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4270704">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4270704</a> |
| 690900002    | INSPECTION APPROVED  | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4275932">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4275932</a> |
| 690900003    | INSP Location ID 440549 CE and P Facility ID 436375 20170920 Photo | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4275933">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4275933</a> |