

**Inspection Photos**  
**Location Name: Ruebel et al 1-4**  
**API: 05-001-08755**



**Wellhead**



**Battery**

**Inspection Photos**  
**Location Name: Ruebel et al 1-4**  
**API: 05-001-08755**



**Separator**



**Riser at Separator Detail, Corrective Action: Leaking Hammer Union, Stained Soil.**



**Inspection Photos**  
**Location Name: Ruebel et al 1-4**  
**API: 05-001-08755**



**North Production Tank Detail, Corrective Action: Staining on Side of Tank.**



**South Production Tank Detail, Corrective Action: Stained soil at base.**