

**Inspection Photos**  
**Location Name: Ruebel et al 1-3**  
**API: 05-001-08732**



**Wellhead, Corrective Action: Packing in master valve appears to be leaking causing stained soil.**



**Battery, Corrective Action: Fencing damage.**

**Inspection Photos**  
**Location Name: Ruebel et al 1-3**  
**API: 05-001-08732**



**Separator & Meter Run, Corrective Action: Fencing damage.**

