

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/09/2017

Submitted Date:

11/14/2017

Document Number:

674901964**FIELD INSPECTION FORM**
 Loc ID 333773 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10464Name of Operator: CATAMOUNT ENERGY PARTNERS LLCAddress: 1801 BROADWAY #1000City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Inspections, All		inspections@catamountep.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
295625	WELL	PR	05/09/2011	GW	067-09534	IGE 139	EI

General Comment:

On November 9, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Catamount Energy Partners LLC IGE #139. For the most recent field inspection report of this facility, please refer to document #680601908.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action	L		Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Free standing sign near well head.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Emergency contact information on well head sign. Phone number used by COGCC staff to report leaking valve on produced water AST. Third party answering service reached.		
Corrective Action:			Date:
Good Housekeeping:			
Type	STORAGE OF SUPL		
Comment:	Flat bed gooseneck trailer with joints of tubing parked in northwest corner of location.		
Corrective Action:	Comply with Rule 603.f.		Date: 12/14/2017
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
Produced Water	Truck Loadout	<= 1 bbl	
Comment:	Valve at load out for produced water tank was dripping during this field inspection. Emergency contact number reached a third party answering service. Lease operator came by and tightened bull plug in valve.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC SW EPS.		Date: 11/15/2017
In Containment: Yes			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Flow Line	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Vertical Heated Separator	# 1		
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	300 BBLs	STEEL AST		37.099680,-107.719552	

Comment: [Load out valve was leaking during this inspection.](#)

Corrective Action:		Date:	
--------------------	--	-------	--

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	

Comment:

Corrective Action:		Date:	
--------------------	--	-------	--

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	295625	Type:	WELL	API Number:	067-09534	Status:	PR	Insp. Status:	EI

--

Environmental**Spills/Releases:**

Type of Spill: PRODUCED WATER

Estimated Spill Volume: _____

Comment: Load out valve on AST was leaking during this inspection.

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC SW EPS.

Date: 11/15/2017

Reportable: NO

GPS: Lat 37.099685

Long -107.719657

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat

Long

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass	Gravel				
Compaction	Pass	Compaction	Pass			
Rip Rap	Pass	Culverts	Pass			
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On November 9, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Catamount Energy Partners LLC IGE #139. For the most recent field inspection report of this facility, please refer to document #680601908. During this field inspection, the load out valve on the produced water AST was leaking fluids. The emergency contact number on the location sign was used to notify a third party answering service of the release. A Catamount lease operator came by and stopped the release.	hughesj	11/14/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401458406	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4301190
674901965	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4301189