

Location

Overall Good:

Signs/Marker:

Type	DRILLING/RECOMP		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type: Flow Line	# 2		corrective date
Comment:	1-2" and 1-1" steel risers		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 424477 Type: WELL API Number: 123-34053 Status: PR Insp. Status: PA

BradenHead

Comment: Bradenhead valve is exposed at surface.

Corrective Action:

Date:

Workover

Comment: MIRU IPS wireline, RIH with junk basket/guage ring combination to 7150' KB, POOH with tools, RIH and set 4 1/2" 10K CIBP @ 7133' KB, POOH with setting tool, RDMO wireline.

Corrective Action:

Date:

Facility ID: 424479 Type: WELL API Number: 123-34055 Status: PR Insp. Status: PA

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
680705050	Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4308166