

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/15/2017

Submitted Date:

11/17/2017

Document Number:

674901976**FIELD INSPECTION FORM**
 Loc ID 326343 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 380 AIRPORT RDCity: DURANGO State: CO Zip: 81303**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**13 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, All		SanJuanCOGCC@bp.com	SW Inspection Reports
Fischer, Alex		alex.fischer@state.co.us	
Beebe, Sabre	970-375-7530	Sabre.Beebe@bp.com	SW Inspection Reports
Leonard, Mike		mike.leonard@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216267	WELL	SI	08/01/2017	GW	067-07873	SEMLER A 1	EI

General Comment:

On November 15, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Semler A #1. For the most recent field inspection report of this facility, please refer to document #667100110.

Location				
Lease Road:				
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	TANK LABELS/PLACARDS			
Comment:	PBV has label and placard on metal containment ring.			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	Free standing sign near entrance to location has broken off of its base and is illegible.			
Corrective Action:	Install sign to comply with Rule 210.b			Date: 12/18/2017
Emergency Contact Number:				
Comment:	Illegible location sign.			
Corrective Action:				Date: _____
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	PUMP JACK			
Comment:	Sound walls on south and east sides of pump jack.			
Corrective Action:				Date:
Type	PUMP JACK			
Comment:	Guard fencing.			
Corrective Action:				Date:
Equipment:				
Type: Prime Mover	# 1			corrective date
Comment:	Electric motor.			
Corrective Action:				Date:
Type: Bird Protectors	# 1			
Comment:				
Corrective Action:				Date:
Type: Ancillary equipment	# 1			
Comment:	Telemetry			
Corrective Action:				Date:

Type: Pump Jack	# 1	
Comment:	In operation during this field inspection.	
Corrective Action:		Date:
Type: Ancillary equipment	# 1	
Comment:	Electrical supply equipment.	
Corrective Action:		Date:
Type: Vertical Heated Separator	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV STEEL		37.135233,-107.673208
Comment:					
Corrective Action:					Date:

Paint

Condition	Inadequate	
Other (Content)		
Other (Capacity)	95 bbl.	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	216267	Type:	WELL	API Number:	067-07873	Status:	SI	Insp. Status:	EI

--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Culverts	Pass			
Compaction	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On November 15, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Semler A #1. For the most recent field inspection report of this facility, please refer to document #667100110. During this field inspection it was noted that the location sign has broken off of its base and is illegible.	hughesj	11/17/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401463535	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4305524
674901977	Inspection photos.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4305520