

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/17/2017

Submitted Date:

11/24/2017

Document Number:

688300667**FIELD INSPECTION FORM**

Loc ID 338217 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10489Name of Operator: AUGUSTUS ENERGY RESOURCES LLCAddress: 2016 GRAND AVENUE #ACity: BILLINGS State: MT Zip: 59102**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**15 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Young, Rob		rob.young@state.co.us	COGCC EPS
Leonard, Mike		mike.leonard@state.co.us	COGCC QA
Jones, Greg	(970) 332-3585	gjones@augustusenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
293782	WELL	PR	03/28/2008	GW	125-11102	SCHOBE 22-01	PR

**General Comment:**

Routine Inspection

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	@ CR EE		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-332-3585

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	Stained soil at wellhead from stuffing box leak (see attached photo).		
Corrective Action:	Properly treat or dispose of oily waste in accordance with Rule 907.e. Contact area COGCC EPS.	Date:	11/28/2017

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				

<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:	steel panels		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	steel panels		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 3		
Comment:	Two sheds, solar panel, radio telemetry, 43 psi on flowline		
Corrective Action:		Date:	
Type: Flow Line	# 7		
Comment:	IN USE: At GMR 3-2", 2-2" and 1-2" with a 1-4" steel risers		
Corrective Action:		Date:	
Type: Vertical Separator	# 3		
Comment:	partially buried		

Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	electric motor, electri panel		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	concrete pad		
Corrective Action:		Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

### Location Construction

Location ID: 293782 CDP: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

#### Form 2A COAs:

**Comment:** No COAs.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

#### Wildlife BMPs:

**Comment:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Comment:** \_\_\_\_\_

**Corrective Action:** \_\_\_\_\_

Date: \_\_\_\_\_

#### On Site Inspection (305):

##### Surface Owner Contact Information:

Name: \_\_\_\_\_

Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Cell Phone: \_\_\_\_\_

##### Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_

Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

##### LGD Contact Information:

Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Agreed to Attend: \_\_\_\_\_

##### Summary of Landowner Issues:

\_\_\_\_\_

##### Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

##### Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Inspected Facilities**Facility ID: 293782 Type: WELL API Number: 125-11102 Status: PR Insp. Status: PR**Producing Well**Comment: [PR. Sep 2017 production reported to COGCC database.](#)

Corrective Action:

Date:

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688300698	Augustus Schobe 22-1	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4309704">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4309704</a>