

Inspection Photos
Location Name: Red Mesa Holdings JCK #3
API: 05-067-06033



JCK #3 wellhead.



Impacted material excavated from around wellhead.



Inspection Photos
Location Name: Red Mesa Holdings JCK #3
API: 05-067-06033



Silt fence installed by A+ Well Services.



Cutting off wellhead.



Inspection Photos
Location Name: Red Mesa Holdings JCK #3
API: 05-067-06033



Impacted material surrounding flow lines.



Flowline terminations near cut off well head.

Inspection Photos
Location Name: Red Mesa Holdings JCK #3
API: 05-067-06033



Back hoe digging perimeter trench around impacted material.



Close up of cut off casing.

Inspection Photos
Location Name: Red Mesa Holdings JCK #3
API: 05-067-06033



Containment trench dug around stained soil.



Photo of containment trench on downhill sides of stain soil stockpile.