

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/21/2017

Submitted Date:

11/27/2017

Document Number:

674901978**FIELD INSPECTION FORM**
 Loc ID 325267 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10254Name of Operator: RED MESA HOLDINGS/O&G LLCAddress: 5619 DTC PARKWAY - STE 800City: GREENWOOD State: CO Zip: 80111**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Andrews, Dave		david.andrews@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214432	WELL	SI	06/30/2011	OW	067-06033	J C K 3	EI

General Comment:

On November 21, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Red Mesa Holdings JCK #3. For the most recent field inspection report of this facility, please refer to document #680602070. COGCC Regional Engineer Mark Weems and SW Field Inspector Cal St. John were on site during this field inspection. An A+ Well Services rig crew was on site to continue PA operations.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Pump Jack	# 1		corrective date
Comment:	Pump jack has been moved from wellhead for PA.		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: 214432	Type: WELL	API Number: 067-06033	Status: SI	Insp. Status: EI

--

Environmental**Spills/Releases:**

Type of Spill: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____ Comment: _____

Waste Management:

Type	Management	Condition	GPS (Lat) (Long)	
Oily Soil	Piles	Adequate	37.090727	-108.122810
Comment	Trench has been dug on downhill side of stockpiled material removed from around the wellhead.			
Corrective Action				Date: _____

Spill/Remediation:

Comment: _____

Corrective Action: _____ Date: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Silt Fences	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On November 21, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Red Mesa Holdings JCK #3. For the most recent field inspection report of this facility, please refer to document #680602070. COGCC Regional Engineer Mark Weems and SW Field Inspector Cal St. John were on site during this field inspection. An A+ Well Services rig crew was on site to continue PA operations. During this site visit the well head was cut off in preparation of welding on the PA well identification plate. The surface casing was not cemented to surface as the well file indicated. Plans to cement the surface casing were made. A trench was dug on the downhill side of the stockpiled soil removed from around the wellhead, until the soil can be disposed of.	hughesj	11/27/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674901979	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4310396