



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the western portion of the project area from the southwestern corner facing northward.



Photo 3. View of the eastern portion of the project area from the northeastern corner facing southward.



Photo 4. View of the erosion occurring at the access road entrance. Ditch is full of sediment and stormwater is diverted and flows across lease road.



Photo 5. View of area in the western project area where concentrated flows are eroding and stormwater controls need maintenance.



Photo 6. View of erosional channel forming at the well pad entrance where diverted stormwater flows off of the eastern well pad.