

Inspection Photos
Location Name: Haller 32-12
API: 05-123-08513



Location is within an exception zone, repair or install berms or other secondary containment devices per Rule 604.c.(3)B.

Wellhead sign

Well motor mounts oil soaked dirt