

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/28/2017

Submitted Date:

11/30/2017

Document Number:

680302755**FIELD INSPECTION FORM**Loc ID 312314 Inspector Name: SCHURE, KYM On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 31257Name of Operator: FRITZLER RESOURCES INCAddress: P O BOX 114City: FORT MORGAN State: CO Zip: 80701**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:13 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Young, Rob		rob.young@state.co.us	
FRITZLER, EUGENE	(970) 867-9388	gfritzler@bresnan.net	
Quint, Craig		craig.quint@state.co.us	
Axelson, John		john.axelson@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221192	WELL	PR	02/10/2006	OW	075-09318	FEHRINGER 1	PR

General Comment:

Routine Site Inspection FIR NOTE TO OPERATOR: Please read entire FIR and respond to CA dates. Send FI Kym Schure a Form 42 verifying that CA's have been performed. Follow-up field inspections scheduled for (10) days after receipt of this FIR.

Location				
Lease Road:				
Type	Access			
comment:	Two track			
Corrective Action	L		Date:	
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Satisfactory			
Corrective Action:			Date:	
Emergency Contact Number:				
Comment:	Satisfactory			
Corrective Action:				Date: _____
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
Crude Oil		<= 1 bbl		
Comment:	Crude Oil ring surrounding edge of PW pit @ fluid level.			
Corrective Action:	Remove/Remediate Crude Oil ring on inside edge of PW pit and all affected soils on inside berm of PW pit. (48) hours allowed to remove/remediate.			Date: 12/02/2017
Lube Oil	Pump Jack	<= 1 bbl		
Comment:	Gear box leak has reached soil at PJ.			
Corrective Action:	Remove/Remediate affected soils at PJ. Repair gear box leak. (48) hours to remedy affected soils.			Date: 12/02/2017
In Containment: Yes				
Comment:	Please send Field Inspector Schure a Form 42 verifying compliance has been performed. Follow-up Field Inspections scheduled for (10) days after receipt of this FIR.			
<input checked="" type="checkbox"/> Multiple Spills and Releases?				
Equipment:				
Type: Prime Mover	# 1			corrective date
Comment:	NG Engine			
Corrective Action:				Date:
Type: Pump Jack	# 1			
Comment:				
Corrective Action:				Date:
Type: Ancillary equipment	# 1			
Comment:	Propane tank			
Corrective Action:				Date:
Type: Vertical Heated Separator	# 1			
Comment:				
Corrective Action:				Date:

Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLS	PBV STEEL		40.992050,-103.181760	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	2	300 BBLS	STEEL AST		40.992340,-103.181760	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: 221192	Type: WELL	API Number: 075-09318	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Pumping OW			
Corrective Action:				Date:

--	--	--	--	--

Environmental**Spills/Releases:**

Type of Spill: OIL

Estimated Spill Volume: _____

Comment: Quantity/Volume of CO undetermined. Crude Oil ring surrounding PW pit at or near fluid level. (48) hours to remove/remediate.

Corrective Action: Remove/Remediate Crude Oil ring surrounding inside face of PW pit berm.
Remove/Remediate effected soils within inside face of berm @ PW pit.

Date: 12/02/2017

Reportable: YES

GPS: Lat 40.992050

Long -103.181760

Proximity to Surface Water:

Depth to Ground Water:

Water Well Complaint:

Lat

Long

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	In Process	Other	In Process			

Comment: Use BMP's for stormwater erosion management

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NO

Pit ID:

Lat: 40.992050Long: -103.181760

Reference Point: _____

Other: _____

Length: _____

Width: _____

Lining:

Liner Type:

Liner Condition:

Comment: Crude Oil ring surrounding PW pit @ fluid level.

Corrective Action

Remove/Remediate Crude Oil ring and affected soils @ PW pit. (48) hours to remove/remediate.Date: 12/02/2017c**Fencing:**

Fencing Type:

Fencing Condition:

Comment:

Corrective Action

Date:

Netting:

Netting Type:

Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present:

Oil Accumulation:

2+ feet Freeboard:

Comment:

Corrective Action

Date:

COGCC Comments

Comment

User

Date

NOTE TO OPERATOR:Read FIR completely and respond to CA's cited. Send Field Inspector Schure a Form 42 verifying compliance. Follow-up FIR scheduled for (10) days after receipt of this FIR.

schureky

11/30/2017