

Inspection Photos
Location Name: Tiffany #1R
API: 05-067-08737



Rip rap run down in SW corner of location requires maintenance.



Erosional channel along western edge of location.

Inspection Photos
Location Name: Tiffany #1R
API: 05-067-08737



Location berm has been breached.



Run on control berm has filled in with sediment.