

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/22/2017

Submitted Date:

11/30/2017

Document Number:

674901985**FIELD INSPECTION FORM**

Loc ID 385876 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100264Name of Operator: XTO ENERGY INCAddress: 600 E EXCHANGE AVECity: FORTH WORTH State: TX Zip: 76164**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:11 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|------------------|--------------|-------------------------------|---------------------------------------|
| Beaty, Brent | 505-330-3210 | brent_beaty@xtoenergy.com | SW Inspection Reports |
| Trobaugh, Robert | 505-333-3185 | robert_trobaugh@xtoenergy.com | SW Inspection Reports |
| Fischer, Alex | | alex.fischer@state.co.us | |
| Woolley, Jeff | 505-333-3222 | Jeff_Woolley@xtoenergy.com | SW Inspection Reports |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 417451 | WELL | PR | 10/16/2010 | GW | 067-09816 | HEIN 1-2 | EI |

General Comment:

On November 22, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the XTO Hein #1-2. For the most recent field inspection report of this facility, please refer to document #674601829.

Location

| | | | |
|--------------------|--------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | | | |
| Corrective Action | | Date: | |

Overall Good: ☒

| | | | |
|----------------------|--|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Free standing sign near location entrance. | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|---|-------|--|
| Emergency Contact Number: | | | |
| Comment: | Operator contact information posted on location sign. | | |
| Corrective Action: | | Date: | |

Overall Good: ☐

| | | | | | |
|----------------|------|--------|--|--|--|
| Spills: | | | | | |
| Type | Area | Volume | | | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | |
|--------------------|--|-------|--|
| Fencing/: | | | |
| Type | PUMP JACK | | |
| Comment: | Stock panel fencing and partial sound walls. | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------------|-----|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Deadman # & Marked | # 4 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Pump Jack | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Vertical Heated Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------|----------------------|-------|--|
| Type: Prime Mover | # 1 | | |
| Comment: | Natural gas powered. | | |
| Corrective Action: | | Date: | |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| Inspected Facilities | | | | | | | | | |
|----------------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 417451 | Type: | WELL | API Number: | 067-09816 | Status: | PR | Insp. Status: | EI |

| |
|--|
| |
|--|

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|----------------------------|
| Berms | Pass | Compaction | Pass | Material Handling And Spill Prevention | Pass | Drip tray for prime mover. |
| Compaction | Pass | Culverts | Pass | | | |

Comment: [Erosional channels beginning to form along southern edge of location.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

| Comment | User | Date |
|---|---------|------------|
| On November 22, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the XTO Hein #1-2. For the most recent field inspection report of this facility, please refer to document #674601829. | hughesj | 11/30/2017 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------------|---|
| 674901986 | Inspection Photos 11.22.17 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4314464 |