

**Inspection Photos**  
**Location Name: Tiffany Lease Tank Battery**  
**Facility ID: 453284**



**Standing water in secondary containment area.**



**Damp area adjacent to SW corner of containment area.**

**Inspection Photos**  
**Location Name: Tiffany Lease Tank Battery**  
**Facility ID: 453284**



**Other damp areas along southern edge of containment area.**



**Patched liner in SW corner of containment area.**

**Inspection Photos**  
**Location Name: Tiffany Lease Tank Battery**  
**Facility ID: 453284**



**Standing water and white residue inside secondary containment area.**



**Damp soil outside of secondary containment ring.**

**Inspection Photos**  
**Location Name: Tiffany Lease Tank Battery**  
**Facility ID: 453284**



**Load out valve was leaking upon arrival. Drip pot is cracked and not functioning properly.**



**Wet area east of tank battery.**

**Inspection Photos**  
**Location Name: Tiffany Lease Tank Battery**  
**Facility ID: 453284**



**Damp soil and white residue in northwest corner of tank battery.**



**White residue and damp areas on north and east side of tank battery.**

**Inspection Photos**  
**Location Name: Tiffany Lease Tank Battery**  
**Facility ID: 453284**



**Standing water around facility equipment on east side of tank battery.**



**Cap on load out line was tightened by XTO representative during inspection of facility.**