

Inspection Photos
Location Name: Wickstrom #6-4
API: 05-123-38576
Inspection Date: November 28, 2016



Photo #1 – Well sign at pump jack shed.



Photo #2 – View of wellhead, looking northwest. Note localized, oil-stained soil at wellhead and day tank at SE corner of pump jack lacking secondary containment device.

Inspection Photos
Location Name: Wickstrom #6-4
API: 05-123-38576
Inspection Date: November 28, 2016



Photo #3 – Oily rag remains tied to wellhead.



Photo #4 – Localized, oil-stained soil beneath SW corner of pump jack.

Inspection Photos
Location Name: Wickstrom #6-4
API: 05-123-38576
Inspection Date: November 28, 2016



Photo #5 – Oil-stained soil beneath NW corner of pump jack.



Photo #6 – Oil-stained soil beneath prime mover (1).

Inspection Photos
Location Name: Wickstrom #6-4
API: 05-123-38576
Inspection Date: November 28, 2016



Photo #7 – Oil-stained soil beneath prime mover (2).



Photo #8 – Chemical storage inside of pump jack shed.