

- Robin Frazier GU PLA 9 1
- 05-067-07588



Photo 1: Wellhead sign. Previous inspection document number 685303916.

- Robin Frazier GU PLA 9 1
- 05-067-07588



Photo 2: Wellhead sign. Current inspection.

- Robin Frazier GU PLA 9 1
- 05-067-07588



**Photo 3: Painted, plugged, and tagged unused riser/flowline.**  
**Previous inspection document number 685303916.**

- Robin Frazier GU PLA 9 1
- 05-067-07588



**Photo 4: Painted, plugged, and tagged unused riser/flowline.**  
**Current inspection.**

- Robin Frazier GU PLA 9 1
- 05-067-07588



**Photo 5: Valve, nipple, and production related materials at wellhead. Previous inspection document number 685303916.**

- Robin Frazier GU PLA 9 1
- 05-067-07588



**Photo 6: Valve, nipple, and production related materials at wellhead. Current inspection.**



- Robin Frazier GU PLA 9 1
- 05-067-07588



**Photo 7: Polished rod at wellhead. Previous inspection document number 685303916.**

- Robin Frazier GU PLA 9 1
- 05-067-07588



**Photo 8: Polished rod at wellhead. Current inspection.**

- Robin Frazier GU PLA 9 1
- 05-067-07588



**Photo 9: Plastic debris along E access road 1. Current inspection.**

- Robin Frazier GU PLA 9 1
- 05-067-07588



**Photo 10: Plastic debris along E access road 2. Current inspection.**

- Robin Frazier GU PLA 9 1
- 05-067-07588



**Photo 11: Framing around compressor where plastic debris is tearing away from. Current inspection.**

- Robin Frazier GU PLA 9 1
- 05-067-07588



**Photo 12: Painted and tagged stainless steel line at gas meter house. Current inspection.**