

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/04/2017

Submitted Date:

12/05/2017

Document Number:

685304025**FIELD INSPECTION FORM**Loc ID 333122 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 380 AIRPORT RDCity: DURANGO State: CO Zip: 81303**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments3 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	COGCC
Leonard, Mike		mike.leonard@state.co.us	
Beebe, Sabre	970-375-7530	Sabre.Beebe@bp.com	SW Inspection Reports
Inspections, All		SanJuanCOGCC@bp.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215982	WELL	PR	11/18/2014	GW	067-07588	Robin Frazier GU PLA 9 1	PR

General Comment:

Inspection completed as follow up to previous inspection document number 685303916.

Corrective actions from previous inspection have not been completed. Corrective action dates remain the same to reflect days of non-compliance. Report contains comment and additional corrective action. See Good Housekeeping for additional details.

See link at end of report for path to downloadable inspection pictures.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: No emergency number or operator contact number on wellhead sign. Corrective action not completed. Corrective action date remains the same to document days of non-compliance.

Corrective Action: Install sign to comply with Rule 210.b.

Date: 11/26/2017

Good Housekeeping:

Type TRASH

Comment: Plastic from compressor walls is tearing away and becoming trapped in vegetation along the E edge of access road.

Corrective Action: Clean up and remove plastic debris from edge of access road and from framing to comply with Rule 603.f.

Date: 12/15/2017

Type UNUSED EQUIPMENT

Comment: Identified (1) unused riser/flowline. 1" steel supply gas line from separator outlet to wellhead. Wellhead riser tagged, painted, and plugged. Line has not been abandoned at time of re-inspection.

Corrective Action:

Date:

Type UNUSED EQUIPMENT

Comment: Polish rod, nipple, valve, and production related items at wellhead. Corrective action not completed. Corrective action date remains the same to document days of non-compliance.

Corrective Action: Remove unused equipment to comply with Rule 603.f.

Date: 11/26/2017

Overall Good: ☐**Spills:**

Type Area Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected FacilitiesFacility ID: 215982 Type: WELL API Number: 067-07588 Status: PR Insp. Status: PR**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685304035	Inspection pictures.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4318412