

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/22/2017

Submitted Date:

11/30/2017

Document Number:

674901982**FIELD INSPECTION FORM**

Loc ID _____ Inspector Name: _____ On-Site Inspection
306777 _____ Hughes, Jim _____ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100264Name of Operator: XTO ENERGY INCAddress: 600 E EXCHANGE AVECity: FORTH WORTH State: TX Zip: 76164**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:13 Number of Comments1 Number of Corrective Actions

-
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Trobaugh, Robert	505-333-3185	robert_trobaugh@xtoenergy.com	SW Inspection Reports
Fischer, Alex		alex.fischer@state.co.us	
Woolley, Jeff	505-333-3222	Jeff_Woolley@xtoenergy.com	SW Inspection Reports
Beaty, Brent	505-330-3210	brent_beaty@xtoenergy.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
264203	WELL	PR	07/11/2002	GW	067-08737	TIFFANY 1R	EI

General Comment:

On November 22, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the XTO Tiffany #1R. For the most recent field inspection report of this facility, please refer to document #674601828.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign mounted to meter run.		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	Operator contact information posted on location sign.		
Corrective Action:			Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Stock panel fencing around well head.		
Corrective Action:			Date:
Type	PUMP JACK		
Comment:	Guard fencing and partial sound walls.		
Corrective Action:			Date:

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:

Type: Ancillary equipment	# 1		
Comment:	Telemetry		
Corrective Action:			Date:
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:			Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 264203 Type: WELL API Number: 067-08737 Status: PR Insp. Status: EI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Fail	Culverts	Pass	Material Handling And Spill Prevention	Pass	Drip tray for prime mover.
Rip Rap	Fail					
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Secondary containment for lube oil container.

Comment: Rip rap run down at location berm out fall (SW corner) requires maintenance. Animal burrows are affecting BMP. Run on control berm along northern edge of location has been breached and has filled in with sediment. Erosional channels are forming on the cut slope.

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 12/29/2017

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
On November 22, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the XTO Tiffany #1R. For the most recent field inspection report of this facility, please refer to document #674601828. Rip rap run down at location berm out fall (SW corner) requires maintenance. Run on control berm along northern edge of location has been breached and has filled in with sediment. Erosional channels are forming on the cut slope.	hughesj	11/30/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401472890	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4314366
674901984	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4314361