

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/30/2017

Submitted Date:

12/01/2017

Document Number:

679700678**FIELD INSPECTION FORM**Loc ID 329266 Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
MacLaren, Joe		joe.maclaren@state.co.us	COGCC Engineering Integrity Inspector
Greg Becker		gregory.becker@greeleygov.com	Greeley Fire Department
Inspections, Noble		NBL_DJBU_Inspections@NB LENERGY.COM	
Axelson, John		john.axelson@state.co.us	COGCC East Environmental Supervisor

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
249282	WELL	SI	04/01/2017	OW	123-17084	MCINTYRE 34-16	EI
453260	SPILL OR RELEASE	AC			-	McIntyre 34-16 flowline	EI

General Comment:

COGCC Environmental Staff Inspection in response to suspected release of E&P Waste in Rover Run Dog Park

Inspected Facilities									
Facility ID:	<u>249282</u>	Type:	<u>WELL</u>	API Number:	<u>123-17084</u>	Status:	<u>SI</u>	Insp. Status:	<u>EI</u>
Facility ID:	<u>453260</u>	Type:	<u>SPILL OR</u>	API Number:	<u>-</u>	Status:	<u>AC</u>	Insp. Status:	<u>EI</u>

Environmental**Spill/Remediation:**

Comment: COGCC Environmental Staff responded to the City of Greeley Rover Run Dog Park to investigate a suspected release of E&P Waste from an abandoned flowline. COGCC Environmental Staff met onsite with the City of Greeley Fire Department Personnel. Fire Department Personnel advised COGCC that a citizen had contacted the City of Greeley park staff on 11/21/2017 to report oil bubbling from the ground. Park staff were unable to locate the incident until the citizen reported the oil bubbling again on 11/29/2017 and park staff located the area of concern. SRC Energy agreed to excavate the area and reportedly completed the excavation on the morning of 11/30/2017. Greeley Fire Department contacted COGCC and COGCC personnel arrived onsite 11/30/2017 and observed an area that was recently excavated and backfilled with clean material. Oil impacted soil remained on the surface in the area of the excavation. COGCC contacted Noble Energy who indicated they would be responsible for remediation of the flowline release. Noble indicated that utility locates had been requested and excavation to investigate and remediate the release would commence on 12/5/2017.

Corrective Action: Operator has submitted Form 19 Initial Report. Form 19 Supplemental Report is due 12/9/2017.

Date: 12/09/2017

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ **Wildlife Protection Devices (fired vessels):** _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401473615	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4314964
679700680	Photo of Release Area 11-30-2017	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4314957