

Environmental

Spills/Releases:

Type of Spill: PRODUCED WATER

Estimated Spill Volume: 5

Comment: Site visit to observe remediation under REM 10748. Temp 14F and windy. Dig and haul of spill area for offsite disposal by Knowles construction. Trackhoe, loader and 20cy dumps on location. Meet with Roberto onsite. Excavation is ~15 feet deep. Leaking pipe has been taken out of service with section cutout and both ends capped. No visible staining or odors in excavation.

Corrective Action: Continue excavation until all confirmation samples are Table 910-1 compliant as demonstrated by laboratory analyses. Assess potential groundwater contamination via monitoring wells and if contamination exceeds Table 910-1 submit remediation plan under another Supplemental F-27.

Date: 12/31/2017

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690300176	Insp photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4321257