

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/06/2017

Submitted Date:

12/08/2017

Document Number:

678301299

FIELD INSPECTION FORM

Loc ID 317790 Inspector Name: GINTAUTAS, PETER On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 42640
Name of Operator: HYNDREX RESOURCES
Address: 1531 4TH AVE
City: GREELEY State: CO Zip: 80631-

Findings:

- 6 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Berger, James	(970) 336-8830	jamesberger2@aol.com	All Inspections
Leonard, Mike		mike.leonard@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
453316	TANK BATTERY	AC	12/06/2017		-	Nessu 1,2,3,4,12,14,15,16 battery	EI

General Comment:

[battery not co-located with wells it serves and battery only was inspected at this time](#)

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	The two crude tanks at the battery are not labeled with the volume of the tanks. Produced water tanks sign did indicate volume		
Corrective Action:	Volume of crude tanks not posted on tanks. Install sign to comply with Rule 210.d.(1).c		Date: 02/08/2018
Type	BATTERY		
Comment:			
Corrective Action:			
Date:			
Type	CONTAINERS		
Comment:	2 chemical product containers hand labeled as to type of product as shown in attached photos. Third chemical container labeled but label has become faded and illegible		
Corrective Action:	Install sign to comply with Rule 210.d.(2)		Date: 02/08/2018
Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: <input type="text"/>
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	unused parts of pumpjack assembly as shown in attached photo		
Corrective Action:	Comply with Rule 603.f .		Date: 03/12/2018
Type	TRASH		
Comment:	broken oil drum as shown in attached photos		
Corrective Action:	Comply with Rule 603.f .		Date: 01/08/2018
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	no spills observed at surface		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	TANK BATTERY		
Comment:			
Corrective Action:			
Date:			
Equipment:			
			corrective date
Type: FWKO	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	FIBERGLASS AST		,

Comment:	
Corrective Action:	Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	210bbls
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:	
Corrective Action:	Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		,

Comment:	
Corrective Action:	Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient		Adequate

Comment:	
Corrective Action:	Date:

Venting:

Yes/No	
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 453316 Type: TANK API Number: - Status: AC Insp. Status: EI

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
678301300	Nessu Battery 453316	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4321573