



Photo 1. View of erosion occurring in the eastern portion of the project area. No stormwater controls have been installed.





Photo 2. View of culvert inlet at that was recently cleaned, and sediment placed adjacent and up-slope from the access road. This disturbed soil will erode back to the roadside drainage and expands the disturbance, and needs to be properly managed.





Photo 3. View of area along the access road where sediment and soil has been scraped and placed up-slope of the roadside drainage. Exposed sediment will rapidly erode, and this practice expands project disturbance by smothering vegetation.

