

Inspection Photos
Location Name: Falcon Seaboard 11-90-2
API: 05-051-06139
Inspection Number:685100414



Release south of well, minimal sawdust used as response




Impacted area in relation to equipment and frac lines

Inspection Photos
Location Name: Falcon Seaboard 11-90-2
API: 05-051-06139
Inspection Number: 685200414



Oily and stained material where frac tanks were placed

Inspection Photos
Location Name: Falcon Seaboard 11-90-2
API: 05-051-06139
Inspection Number: 685200414



Impacted material where frac tanks were located

Inspection Photos

Location Name: Falcon Seaboard 11-90-2

API: 05-051-06139

Inspection Number: 685200414



Oily rags and stained soils