

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/01/2017

Submitted Date:

12/05/2017

Document Number:

671000784**FIELD INSPECTION FORM**

Loc ID 429618 Inspector Name: DURAN, JOHN On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10630Name of Operator: ALTA MESA SERVICES LPAddress: 15021 KATY FREEWAY SUITE 400City: HOUSTON State: TX Zip: 77094**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**10 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Johnson, Jerry	361-230-5151/2815300991	jjohnson@altamesa.net	All Inspections.
Sutphin, Dirk		dirk.sutphin@state.co.us	
Jameson, Max	281-9440638/832-453-1783	mjameson@altamesa.net	All Inspections.

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
429619	WELL	SI	08/03/2017	OW	055-06309	Freeman 3-24	PA

General Comment:

Co. Man - Jerry Johnson (Alta Mesa), Hurricane Air & Swabbing, Farmington, NM : Rig and Rig Crew, Topar Welding, Trinidad, CO : Marcus Short.

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	De-high unit		
Corrective Action:		Date:	
Type: Ancillary equipment	# 0		
Comment:	Wellhead and Christmas tree		
Corrective Action:		Date:	
Type: Flare	# 2		
Comment:	Flare box and flare to oil tanks		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition Adequate

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:	With liner			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	400 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:	With liner			
Corrective Action:				Date:

Venting:

Yes/No	
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 429619 Type: WELL API Number: 055-06309 Status: SI Insp. Status: PA

CementCement Contractor

Contractor Name: _____

Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): _____

Cement Volume (sx): _____

Good Return During Job: _____

Cement Type: _____

Comment:

After welder cuts off 7" CSG all the annuluses are topped off with cement sacks (hand mixed) left behind by Halliburton. The 7" CSG is cut 5 ft below surface and a 7" plate us welded on top of 7" CSG and 16" Information plate is tacked onto 13 3/8" CSG. Cellar is back filled with dirt. Site is satisfactory for plugged and abandoned, but not for bond release.

Corrective Action:

The remaining equipment needs to be off site in 3 months after plugging. All reclamation work shall be completed within 12 months on non-crop land after plugging.

Date: 03/05/2018

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On site at 7:00am. Welder arrives at 7:05am. Finishes cutting 7"CSG by 9:05am. The Casing is cut 5 ft below surface. By 9:45am cement topped off last 10 ft in annuluses with bags left behind by Halliburton. By 10:25am welder has 7" plate welded on. By 11:05am welder has tacked 16" Information plate to 13 3/8" CSG. Cellar is backfilled with dirt. No follow up for P/A, but for final reclamation and bond release. Off site at 11:30 am.	duranj	12/04/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401475970	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4317112