

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/04/2017

Submitted Date:

12/05/2017

Document Number:

685304025**FIELD INSPECTION FORM**

Loc ID _____ Inspector Name: _____ On-Site Inspection
333122 _____ St John, William (Cal) _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10000
 Name of Operator: BP AMERICA PRODUCTION COMPANY
 Address: 380 AIRPORT RD
 City: DURANGO State: CO Zip: 81303

Findings:

- 8 Number of Comments
3 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Leonard, Mike		mike.leonard@state.co.us	
Inspections, All		SanJuanCOGCC@bp.com	SW Inspection Reports
Beebe, Sabre	970-375-7530	Sabre.Beebe@bp.com	SW Inspection Reports
Labowskie, Steve		steve.labowskie@state.co.us	COGCC

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215982	WELL	PR	11/18/2014	GW	067-07588	Robin Frazier GU PLA 9 1	PR

General Comment:

[Inspection completed as follow up to previous inspection document number 685303916.](#)

[Corrective actions from previous inspection have not been completed. Corrective action dates remain the same to reflect days of non-compliance. Report contains comment and additional corrective action. See Good Housekeeping for additional details.](#)

[See link at end of report for path to downloadable inspection pictures.](#)

Location

Overall Good:

Emergency Contact Number:

Comment: No emergency number or operator contact number on wellhead sign. Corrective action not completed. Corrective action date remains the same to document days of non-compliance.

Corrective Action: Install sign to comply with Rule 210.b.

Date: 11/26/2017

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Polish rod, nipple, valve, and production related items at wellhead. Corrective action not completed. Corrective action date remains the same to document days of non-compliance.		
Corrective Action:	Remove unused equipment to comply with Rule 603.f.	Date:	11/26/2017
Type	UNUSED EQUIPMENT		
Comment:	Identified (1) unused riser/flowline. 1" steel supply gas line from separator outlet to wellhead. Wellhead riser tagged, painted, and plugged. Line has not been abandoned at time of re-inspection.		
Corrective Action:		Date:	
Type	TRASH		
Comment:	Plastic from compressor walls is tearing away and becoming trapped in vegetation along the E edge of access road.		
Corrective Action:	Clean up and remove plastic debris from edge of access road and from framing to comply with Rule 603.f.	Date:	12/15/2017

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 215982 Type: WELL API Number: 067-07588 Status: PR Insp. Status: PR

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401477106	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4318413
685304035	Inspection pictures.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4318412