

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/12/2017

Submitted Date:

12/12/2017

Document Number:

679903560

FIELD INSPECTION FORM

Loc ID 416393 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 55575
Name of Operator: MCELVAIN ENERGY INC
Address: 1050 17TH ST STE 2500
City: DENVER State: CO Zip: 80265-

Findings:

9 Number of Comments
1 Number of Corrective Actions

Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Cooper, Tony	(303) 893-0933 x331	tony.cooper@mcelvain.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
416400	WELL	PR	07/06/2010	GW	125-11812	Meeker 20-13	PR

General Comment:

[Routine Inspection](#)

Location

Lease Road:			
	Type	Access	
	comment:	Dirt road through pasture	
	Corrective Action:		Date:

Overall Good:

Signs/Marker:			
	Type	WELLHEAD	
	Comment:	Lease sign by metal shed	
	Corrective Action:		Date:

Emergency Contact Number:			
	Comment:	<input type="text"/>	
	Corrective Action:	<input type="text"/>	Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
	Type	WELLHEAD	
	Comment:	Metal panels around wellhead, metal shed and VGS	
	Corrective Action:		Date:

Equipment:			corrective date
Type: Vertical Separator	# 2		
	Comment:	1-Vertical gas separator 50% buried by metal shed 1-Vertical gas separator in metal shed	
	Corrective Action:		Date:
Type: Ancillary equipment	# 1		
	Comment:	Telemetry equipment	
	Corrective Action:		Date:
Type: Gas Meter Run	# 1		
	Comment:	Meter run in metal shed	
	Corrective Action:		Date:

Venting:			
	Yes/No	NO	
	Comment:		
	Corrective Action:		Date:

Flaring:			
Type			

Comment:		
Corrective Action:	Date:	

Inspected Facilities

Facility ID: 416400 Type: WELL API Number: 125-11812 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Fail	Compaction	Pass			

Comment: [Erosion leading off of location and on access needs maintenance](#)

Corrective Action: [Repair and maintain erosion leading off of location to the south. Repair erosion on access](#)

Date: 01/12/2018

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679903565	Location photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4323978