


Inspection Photos
Location Name: Allison Unit #19
API: 05-067-05008



Open topped produced water vessel.



Allison Unit #19 well head.

Inspection Photos
Location Name: Allison Unit #19
API: 05-067-05008



Pit area SE of location with 4" steel pipe outlet.



Bermed area SE of location.

Inspection Photos
Location Name: Allison Unit #19
API: 05-067-05008



View from pit area towards location.



4" steel pipe outlet to pit area. Inlet was not observed during this field inspection.