

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/06/2017

Submitted Date:

12/08/2017

Document Number:

678301299**FIELD INSPECTION FORM**Loc ID 317790 Inspector Name: GINTAUTAS, PETER On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 42640Name of Operator: HYNDREX RESOURCESAddress: 1531 4TH AVECity: GREELEY State: CO Zip: 80631-**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Leonard, Mike		mike.leonard@state.co.us	
Berger, James	(970) 336-8830	jamesberger2@aol.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
453316	TANK BATTERY	AC	12/06/2017		-	Nessu 1,2,3,4,12,14,15,16 battery	EI

General Comment:[battery not co-located with wells it serves and battery only was inspected at this time](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	2 chemical product containers hand labeled as to type of product as shown in attached photos. Third chemical container labeled but label has become faded and illegible		
Corrective Action:	Install sign to comply with Rule 210.d.(2)	Date:	02/08/2018
Type	TANK LABELS/PLACARDS		
Comment:	The two crude tanks at the battery are not labeled with the volume of the tanks. Produced water tanks sign did indicate volume		
Corrective Action:	Volume of crude tanks not posted on tanks. Install sign to comply with Rule 210.d.(1).c	Date:	02/08/2018

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	TRASH		
Comment:	broken oil drum as shown in attached photos		
Corrective Action:	Comply with Rule 603.f .	Date:	01/08/2018
Type	UNUSED EQUIPMENT		
Comment:	unused parts of pumpjack assembly as shown in attached photo		
Corrective Action:	Comply with Rule 603.f .	Date:	03/12/2018

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: no spills observed at surface

☐ Multiple Spills and Releases?**Fencing/:**

Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	

Equipment:

Type: FWKO	# 1		corrective date
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	200 BBLs	FIBERGLASS AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition					
Other (Content)					
Other (Capacity)	210bbls				
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	2	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient		Adequate	
Comment:					
Corrective Action:					

Venting:

Yes/No					
Comment:					
Corrective Action:					Date:

Flaring:

Type				
Comment:				
Corrective Action:				

Inspected FacilitiesFacility ID: 453316 Type: TANK API Number: - Status: AC Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401480920	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4321584
678301300	Nessu Battery 453316	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4321573