

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/15/2017

Submitted Date:

12/15/2017

Document Number:

680402301

FIELD INSPECTION FORM

Loc ID 322010 Inspector Name: BROWNING, CHUCK On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10310
Name of Operator: FRAM OPERATING LLC
Address: 6 SOUTH TEJON STREET #400
City: COLORADO State: CO Zip: 80903

Findings:

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

| Contact Name | Phone | Email | Comment |
|------------------|----------------|----------------------------------|-----------------|
| Browning, Chuck | 970-433-4139 | chuck.browning@state.co.us | Field Inspector |
| Leonard, Mike | | mike.leonard@state.co.us | |
| Cook, David | (719) 314-1623 | dave@framamericas.com | |
| | | dnr_cogccengineering@state.co.us | |
| Labowskie, Steve | | steve.labowskie@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 286535 | WELL | SI | 12/05/2006 | GW | 029-06100 | HAMILTON 33-2 | TA |

General Comment:

Location

| | | | |
|--------------------|-------------------|--------|-------|
| Lease Road: | | | |
| | Type | Access | |
| | comment: | | |
| | Corrective Action | | Date: |
| | Type | Main | |
| | comment: | | |
| | Corrective Action | | Date: |

Overall Good:

| | | | |
|----------------------|--------------------|----------|-------|
| Signs/Marker: | | | |
| | Type | WELLHEAD | |
| | Comment: | | |
| | Corrective Action: | | Date: |

Emergency Contact Number:

| | | | |
|--------------------|--|-------|--|
| Comment: | <input style="width: 95%;" type="text"/> | | |
| Corrective Action: | <input style="width: 95%;" type="text"/> | Date: | <input style="width: 80%;" type="text"/> |

Overall Good:

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

Multiple Spills and Releases?

| | | | |
|------------------|--------------------|--|-------|
| Fencing/: | | | |
| | Type | WELLHEAD | |
| | Comment: | Livestock fence. Repair if requested by landowner. | |
| | Corrective Action: | | Date: |

| | | | |
|-----------------|--------------------|--|-------|
| Venting: | | | |
| Yes/No | NO | | |
| | Comment: | | |
| | Corrective Action: | | Date: |

| | | | |
|-----------------|--------------------|--|-------|
| Flaring: | | | |
| Type | | | |
| | Comment: | | |
| | Corrective Action: | | Date: |

Inspected Facilities

Facility ID: 286535 Type: WELL API Number: 029-06100 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Last MIT 10/23/2012.
No current MIT on record or delinquent as required by Rule 326

Corrective Action: Contact dnr_cogccengineering@state.co.us with resolution plan. Date: 12/29/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---------------------------------|---|
| 680402302 | Inspection photos 12/15/2017 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4327436 |