



Photo 1. View of area near well pad entrance where debris was removed.



Photo 2. View of Russian knapweeds (*Acroptilon repens*) in the southwestern portion of the project area.



Photo 3. View of Russian knapweeds in the southern portion of the project area.