

Inspection Photos

Location Name: Lorenz Farms 22-13

API #: 05-123-19256

Location ID: 330537



Wellhead looking east



2" Ball valve from surface casing to flowline appears to be leaking. Stained soil under valve



Inspection Photos

Location Name: Lorenz Farms 22-13

API #: 05-123-19256

Location ID: 330537



Battery looking east



Produced water vault does not have capacity labeled and does not have NFPA placard

