

Location Name: Magellan #1

API: 05-043-06229

Inspection Date: 12/15/2017



Location Name: Magellan #1

API: 05-043-06229

Inspection Date: 12/15/2017



Location Name: Magellan #1

API: 05-043-06229

Inspection Date: 12/15/2017



Location Name: Magellan #1

API: 05-043-06229

Inspection Date: 12/15/2017



No stormwater BMP's in place to prevent sediment flow off location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Magellan #1

API: 05-043-06229

Inspection Date: 12/15/2017



No stormwater BMP's in place to prevent sediment flow off location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Magellan #1

API: 05-043-06229

Inspection Date: 12/15/2017



Stormwater BMP's



Location Name: Magellan #1

API: 05-043-06229

Inspection Date: 12/15/2017



Inadequate stormwater BMP's. Sediment flow off location observed.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Magellan #1

API: 05-043-06229

Inspection Date: 12/15/2017



Location Name: Magellan #1

API: 05-043-06229

Inspection Date: 12/15/2017



Location Name: Magellan #1

API: 05-043-06229

Inspection Date: 12/15/2017



Venting from open valve pictured was observed during inspection.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Magellan #1

API: 05-043-06229

Inspection Date: 12/15/2017



Location Name: Magellan #1

API: 05-043-06229

Inspection Date: 12/15/2017



Drilling pit

