

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/15/2017

Submitted Date:

12/19/2017

Document Number:

682600406**FIELD INSPECTION FORM**
 Loc ID 436788 Inspector Name: Kosola, Jason On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10412Name of Operator: AUSCO PETROLEUM INCAddress: 113 N SANTA FE AVENUECity: FLORENCE State: CO Zip: 81226**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Goss, Aaron	303-495-0327	agoss@fremontpetroleum.com	All Inspections
Axelson, John		john.axelson@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
437153	WELL	TA	03/31/2016	LO	043-06226	Hudson 1	EI

General Comment:

This is an environmental inspection to document compliance with Notice of Alleged Violation (NOAV) #401263050. At the time of inspection operator has not yet submitted a Form 27 for pit closure as required per NOAV. Operator has been informed of requirement to submit Form 27 and close pit. At the time of issuance of this inspection the operator has begun pit closure and obtained soil samples from pit but no Form 27 has been submitted. AS OF 12/19/2017 OPERATOR IS 310 DAYS PAST DUE ON THIS CORRECTIVE ACTION.

Production not reported. Report production via Form 7 as required by Rule 206. Contact COGCC Production Department. OPERATOR'S MONTHLY REPORT OF OPERATIONS DELINQUENT REPORT (document # 401345280) was issued on 7/18/2017.

Form 1A for operator appears to contain incorrect email addresses for designated agents. Operator shall update Form 1A with correct information.

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT

Type:	Lined:	Pit ID:	Lat:	Long:
Reference Point: <input type="text"/>	Other: <input type="text"/>	Length: <input type="text"/>	Width: <input type="text"/>	

Lining:Liner Type: Liner Condition: Comment:

Drilling pit remains open more than 6 months after drilling and completion activities. See attached photos.
 AS OF 12/19/2017 OPERATOR IS 310 DAYS PAST DUE ON THIS CORRECTIVE ACTION.

Corrective Action

Date: 02/12/2017c

Operator shall submit Form 27 to the area Environmental Protection Specialist (EPS) to document closure of drilling pit. Operator shall comply with applicable COA's on permit outlining pit closure. Operator shall document disposal of pit contents, pit liner and obtain soil samples from bottom of pit to document compliance with COGCC Table 910-1. Sample results and disposal documentation shall be submitted on the Form 27.

Fencing:Fencing Type: Fencing Condition: Comment: Corrective Action Date: **Netting:**Netting Type: Netting Condition: Comment: Corrective Action Date: Anchor Trench Present: Oil Accumulation: 2+ feet Freeboard: Comment: Corrective Action Date: **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682600407	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4331145