

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/08/2017

Submitted Date:

12/20/2017

Document Number:

680602319**FIELD INSPECTION FORM**

Loc ID 325605 Inspector Name: ROY, CATHERINE On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10663Name of Operator: ENDURING RESOURCES LLCAddress: 511 16TH STREET #700City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|--------------|-----------------------------|---|
| Pohl, April | 505-333-1941 | apohl@enduringresources.com | All Inspections Southwest |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 215087 | WELL | PR | 02/12/1993 | GW | 067-06692 | WHEELER 7U-1 | RI |

General Comment:

[This is an interim reclamation and stormwater inspection. Any corrective actions not addressed from previous inspections are still applicable.](#)

| Inspected Facilities | | | | | | | | | |
|----------------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 215087 | Type: | WELL | API Number: | 067-06692 | Status: | PR | Insp. Status: | RI |
| | | | | | | | | | |

| |
|--|
| |
|--|

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: Project area is surrounded by mixed use development and sagebrush/pinyon juniper woodland. Revegetation is progressing within the interim reclamation areas.**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

| | |
|---|---|
| 1003b. Area no longer in use? <u>In</u> 1003c. Compacted areas have been cross ripped? _____ 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____ Cuttings management: _____ 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? <u>In</u> Production areas have been stabilized? _____ Segregated soils have been replaced? _____ | Production areas stabilized ? <u>In</u> |
|---|---|

RESTORATION AND REVEGETATION

Cropland

| | | |
|-------------------------|-------------------|---------------------------------------|
| Top soil replaced _____ | Recontoured _____ | Perennial forage re-established _____ |
|-------------------------|-------------------|---------------------------------------|

Non-Cropland

| | | |
|-------------------------|-------------------|----------------------------|
| Top soil replaced _____ | Recontoured _____ | 80% Revegetation <u>In</u> |
|-------------------------|-------------------|----------------------------|

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment Approximatey 35 musk thistles were observed within the eastern portion of the project area.

Corrective Action Control weeds at the appropriate time but no later than June 15, 2018. Date 06/15/2018

Overall Interim Reclamation In Process

Final Reclamation/ Abandoned Location:

| | |
|---------------------------------------|---|
| Date Final Reclamation Started: _____ | Date Final Reclamation Completed: _____ |
|---------------------------------------|---|

Final Land Use: _____

Reminder: _____

Comment:

| | |
|----------------------|---|
| Well plugged _____ | Pit mouse/rat holes, cellars backfilled _____ |
| Debris removed _____ | No disturbance /Location never built _____ |

| | | |
|----------------------------------|-----------------|------------------------|
| Access Roads Regraded _____ | Contoured _____ | Culverts removed _____ |
| Gravel removed _____ | | |

| | |
|---|---|
| Location and associated production facilities reclaimed _____ | Locations, facilities, roads, recontoured _____ |
|---|---|

| | |
|------------------------------|--------------------------------|
| Compaction alleviation _____ | Dust and erosion control _____ |
|------------------------------|--------------------------------|

| | |
|-------------------------------------|----------------------------------|
| Non cropland: Revegetated 80% _____ | Cropland: perennial forage _____ |
|-------------------------------------|----------------------------------|

| | |
|---------------------|------------------|
| Weeds present _____ | Subsidence _____ |
|---------------------|------------------|

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment:

Corrective Action: Date _____

Overall Final Reclamation _____ Well Release on Active Location ☐ Multi-Well Location ☐

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment: [Stormwater erosion appears to be controlled at this time.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

| | | | |
|---------|-------------|------------|-----------------|
| Permit: | Facility ID | Permit Num | Expiration Date |
| | 288230 | 200100213 | |
| | 288230 | 200100213 | |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 680602320 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4331838 |