



Photo 1. View of the project area from the northern corner facing center.



Photo 2. View of the northern portion of the project area from the northern corner facing westward.



Photo 3. View of the eastern portion of the project area from the northern corner facing southeastward. Revegetation is progressing with grasses and shrubs such as western wheatgrass (*Pascopyrum smithii*) and rubber rabbitbrush (*Chrysothamnus nauseosus*).





Photo 4. View of check dams along access that are full of sediment and need maintenance.