

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/11/2017

Submitted Date:

12/14/2017

Document Number:

674901994

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
324971 _____ Hughes, Jim _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10133
Name of Operator: HILCORP ENERGY COMPANY
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208

Findings:

- 15 Number of Comments
2 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Leonard, Mike		mike.leonard@state.co.us	
Shorty, Priscilla	(505) 324-5188	pshorty@hilcorp.com	
Fischer, Alex		alex.fischer@state.co.us	
Ray, Mandi	(505) 324-5122	mray@hilcorp.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
115849	PIT				-	ALLISON 19	EI
213752	WELL	PR	10/12/1996	GW	067-05008	ALLISON UNIT 19	EI

General Comment:

On December 11, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Hilcorp Energy Co. Allison Unit #19. For the most recent field inspection report for this facility, please refer to document #674601115.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Sign mounted to fencing for produced water vessel.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Sign mounted to fencing for open topped produced water vessel.		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Chemical injection system has label and placard.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	Posted on location sign. Phone number verified while inquiring about access to location.		
Corrective Action:		Date:	
Good Housekeeping:			
Type	WEEDS		
Comment:	Weeds present inside and on secondary containment berm.		
Corrective Action:	Comply with Rule 603.f.	Date:	12/25/2017
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	TANK BATTERY		
Comment:	Post and wire fencing around perimeter of open topped tank.		
Corrective Action:		Date:	
Equipment:			
Type:	Horizontal Heated Separator	# 1	corrective date
Comment:			
Corrective Action:		Date:	
Type:	Ancillary equipment	# 1	
Comment:	Chemical injection system.		

Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Telemetry		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Electrical supply equipment.		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 3		
Comment:	Only three markers observed.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	Open Top		37.002058,-107.562979
Comment:	Expanded metal lid.				
Corrective Action:					Date:

Paint

Condition	Inadequate	
Other (Content)		
Other (Capacity)	120 bbl.	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
--------	----	--

Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 115849 Type: PIT API Number: - Status: Insp. Status: EI

Facility ID: 213752 Type: WELL API Number: 067-05008 Status: PR Insp. Status: EI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Secondary containment for chem. injection system.
		Ditches	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: _____ Lined: NO Pit ID: 115849 Lat: 37.001192 Long: -107.561918

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment:

Corrective Action

Date: c

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment:

Corrective Action

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action

Date: _____

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment: Pit #115849 currently has an unknown status in the COGIS database. Pit observed to the SE of the facility.

Corrective Action Contact COGCC SW EPS for directives per Rule 905.b.

Date: 12/25/2017

COGCC Comments

Comment	User	Date
On December 11, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Hilcorp Energy Co. Allison Unit #19. For the most recent field inspection report for this facility, please refer to document #674601115. Pit Facility ID #115849 is listed in the COGIS database with an unknown status. The operator shall provide a Form 27 per Rule 909.c, for pit closure. A pit was observed to the SE of the location with a 4" steel pipe drain outlet.	hughesj	12/14/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401486578	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4326401
674901995	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4326400