

Inspection Photos 12/20/17
Location Name: Seltzer GU 2-4
API: 05-001-09025



Wellhead and signage



Master Valve – Leak identified at bolt up/ paint removed

Inspection Photos 12/20/17
Location Name: Seltzer GU 2-4
API: 05-001-09025



Tubing Gauge showing current pressure



Horizontal separator – Unused equipment

Inspection Photos 12/20/17
Location Name: Seltzer GU 2-4
API: 05-001-09025



Tubing on North side separator – unused equipment



Production tank – unused equipment; poly hose – unused equipment