

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/11/2017

Submitted Date:

12/15/2017

Document Number:

674901996**FIELD INSPECTION FORM**Loc ID 326584 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10133Name of Operator: HILCORP ENERGY COMPANYAddress: P O BOX 61229City: HOUSTON State: TX Zip: 77208**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**11 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Ray, Mandi	(505) 324-5122	mray@hilcorp.com	
Shorty, Priscilla	(505) 324-5188	pshorty@hilcorp.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258298	WELL	PR	05/07/2001	GW	067-08350	ALLISON UNIT 147	EI

General Comment:

On December 11, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Hilcorp Energy Co. Allison Unit #147. For the most recent field inspection report of this facility, please refer to document #674601114.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Location sign mounted to fencing at tank battery.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	ASTs have Conoco Phillips labels on them. Western tank is labeled out of service.		
Corrective Action:		Date:	

Emergency Contact Number:		
Comment:	Posted on location sign.	
Corrective Action:		Date: _____

Overall Good: ☐

Spills:			
Type	Area	Volume	
Lube Oil	Pump Jack	<= 1 bbl	
Comment:	Concrete pad for pump jack and area near muffler exhaust is stained.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.		Date: 01/15/2018
Produced Water	WELLHEAD	<= 1 bbl	
Comment:	Well head and surrounding area is stained with white residue.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.		Date: 01/15/2018

In Containment: No

Comment: ☒ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	Post and wire perimeter fencing.		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Post and wire perimeter fencing.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Vertical Heated Separator	# 1		
Comment:			

Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Telemetry		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 2		
Comment:	Two anchor markers observed during this inspection.		
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	500 BBLs	HEATED STEEL AST		37.002805,-107.560429
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO
--------	----

Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	258298	Type:	WELL	API Number:	067-08350	Status:	PR	Insp. Status:	EI

--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On December 11, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Hilcorp Energy Co. Allison Unit #147. For the most recent field inspection report of this facility, please refer to document #674601114. During this inspection staining was observed on the well head and surrounding area. The concrete pad and surrounding area are stained near the muffler exhaust.	hughesj	12/15/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401487854	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4327587
674901998	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4327584