

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/09/2017

Submitted Date:

12/22/2017

Document Number:

689400779**FIELD INSPECTION FORM**Loc ID 324458 Inspector Name: CONKLIN, CURTIS On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10515Name of Operator: GUNNISON ENERGY LLCAddress: 1801 BROADWAY #1200City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☐
- FOLLOW UP INSPECTION REQUIRED
-
- ☒
- NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
McWilliams, Dan	(970) 986-2927	dan.mcwilliams@oxbow.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	NW Supervisor

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211687	WELL	PR	08/01/2015	GW	051-06009	FEDERAL 10-90-31	PR

General Comment:

This is a follow up inspection to FIR Doc#689400605. Any corrective actions not addressed from previous inspections are still applicable.

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	NFPA Diamond updated. Corrective action from previous inspection has been met.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	(970) 874-7697	Date: _____
Corrective Action:		

Good Housekeeping:

Type	TRASH		
Comment:	Trash has been removed. Corrective action from previous inspection has been met.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Valves, pipes, and fittings have been secured. Corrective action from previous inspection has been met.		
Corrective Action:		Date:	

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Vegetation and debris has been removed. Corrective action from previous inspection has been met.			

Inspected Facilities									
Facility ID:	211687	Type:	WELL	API Number:	051-06009	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Flowing								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT