

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/15/2017

Submitted Date:

12/19/2017

Document Number:

682600411**FIELD INSPECTION FORM**Loc ID 439554 Inspector Name: Kosola, Jason On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10412Name of Operator: AUSCO PETROLEUM INCAddress: 113 N SANTA FE AVENUECity: FLORENCE State: CO Zip: 81226**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

| Contact Name    | Phone        | Email                      | Comment         |
|-----------------|--------------|----------------------------|-----------------|
| Axelson, John   |              | john.axelson@state.co.us   |                 |
| Housey, Melissa |              | melissa.housey@state.co.us |                 |
| Goss, Aaron     | 303-495-0327 | agoss@fremontpetroleum.com | All Inspections |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 439553      | WELL | DG     |             | LO         | 043-06228 | Marco Polo 1  | EI          |

**General Comment:**

ALLEGED VIOLATION – Document number 401276215 granted a one-time only, extension of the use of the Marco Polo #1 Drilling Pit. The Drilling Pit is to be closed no later than November 15, 2017. Pit remains open as of inspection on 12/15/2017.

Pit netting inadequate. See attached photos.

Production not reported. Report production via Form 7 as required by Rule 206. Contact COGCC Production Department. OPERATOR'S MONTHLY REPORT OF OPERATIONS DELINQUENT REPORT (document # 401345280) was issued on 7/18/2017.

Form 1A for operator appears to contain incorrect email addresses for designated agents. Operator shall update Form 1A with correct information.



**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Drilling PitLined: YESPit ID: Lat: Long: Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: Corrective Action: Date: c**Fencing:**Fencing Type: LivestockFencing Condition: AdequateComment: Corrective Action: Date: **Netting:**Netting Type: MeshNetting Condition: GapsComment: Netting or fencing not maintained and allows wildlife access. Animal tracks observed in pit (see attached photos).Corrective Action: Date: 12/20/2017Anchor Trench Present: Oil Accumulation: 2+ feet Freeboard: Comment: Corrective Action: Date: **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 401491401    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4331152">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4331152</a> |
| 682600412    | Inspection photos    | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4331147">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4331147</a> |