

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/09/2017

Submitted Date:

12/27/2017

Document Number:

688500016**FIELD INSPECTION FORM**Loc ID 318928 Inspector Name: CANFIELD, CHRIS On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 39560Name of Operator: TOP OPERATING COMPANY FDBA MURRAY JAddress: 3609 S WADSWORTH BLVD STE 340City: LAKEWOOD State: CO Zip: 80235**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Axelson, John		john.axelson@state.co.us	
HERRING, MURRAY J	(303) 727-9915 x203	murray.herring@topoperating.com	
HERRING, PAUL	(303) 727-9915	paul.herring@topoperating.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
318928	LOCATION	AC			-	SERAFINI GAS UNIT-62N68W 18NENE	EI

General Comment:

The subject inspection was done on 05/09/2017. An IT problem prevented it from being entered at that time.

Inspected Facilities									
Facility ID:	318928	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	EI

--

Environmental**Spills/Releases:**

Type of Spill: _____

Estimated Spill Volume: _____

Comment: Subject location was inspected to determine if the operator had implemented a Supplemental Environmental Assessment Work Plan (Remediation Project 6883) that was approved by the COGCC on 02/23/2017.

Corrective Action: _____

Date: _____

Reportable: _____

GPS: Lat _____

Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat _____

Long _____

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

COGCC Comments

Comment	User	Date
The operator had not submitted progress reports or monitoring reports subsequent to COGCC approval of supplemental work proposed by the operator on 02/22/2017. It was not possible to determine during the inspection what work, if any, had been done following the approval of the supplemental work plan. The operator's environmental was contacted to ask if a progress report would be forthcoming.	canfielc	12/27/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688500017	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4336063