

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/20/2017

Submitted Date:

12/21/2017

Document Number:

688600161**FIELD INSPECTION FORM**

Loc ID 428669 Inspector Name: BURGER, CRAIG On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 1Name of Operator: UNKNOWN

Address: _____

City: _____ State: _____ Zip: _____

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Andrews, Dave		david.andrews@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
425793	WELL	TA	10/12/2011	LO	077-40017	Lloyd and Lowell 1	TA

General Comment:

Orphan well plugging project. Contractor is RACS.

Inspected FacilitiesFacility ID: 425793 Type: WELL API Number: 077-40017 Status: TA Insp. Status: TA**Workover**

Comment: Picked up power swivel. Drilled with 6.5" bit through fish at 165' (probably wood), bridges at 340' and 400 to 425'. Shale cuttings.
Some oil to the circulation tank then lost circulation (60 bbls) and well went on a vacuum.
Pulled drill string to run camera job tomorrow.

Corrective Action: Plug and abandon.

Date: 12/31/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401493945	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4333288