



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the eastern portion of the project area from the southeastern corner facing northward. Revegetation is progressing with dropseed (*Sporobolus* sp.) and smooth brome (*Bromus inermis*).





Photo 3. View of the southern portion of the project area from the southeastern corner facing westward.



Photo 4. View of the northern portion of the project area from the northwestern corner facing eastward. Dried kochia debris lines this portion of the project area.



Photo 5. View of kochia debris around fired equipment, and blowing within the project area.