

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/27/2017

Submitted Date:

12/28/2017

Document Number:

682600416**FIELD INSPECTION FORM**
 Loc ID \_\_\_\_\_ Inspector Name: Kosola, Jason On-Site Inspection ☐  
 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 10084Name of Operator: PIONEER NATURAL RESOURCES USA INCAddress: 5205 N O'CONNOR BLVD STE 200City: IRVING State: TX Zip: 75039**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Axelson, John		john.axelson@state.co.us	
Distribution, Pioneer	972-444-9001	COGCC.Inspections@pxd.co m	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
411992	WELL	PR		GW	071-09769	Gremlin 23-35	EI
427440	WATER GATHERING SYSTEM/LINE	AC	01/25/2012		-	Pioneer Raton Basin Water Gathering 427440	EI

**General Comment:**

This is an environmental inspection to document status of Spill #453581 reported on the Gremlin 23-35 location (COGCC Form 19# 401495799).

At the time of inspection the spill had ceased and impacts to the spill were confined to the area immediately around the meter house (see attached photos).

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: <u>411992</u>	Type: <u>WELL</u>	API Number: <u>071-09769</u>	Status: <u>PR</u>	Insp. Status: <u>EI</u>
Facility ID: <u>427440</u>	Type: <u>WATER</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>EI</u>

**Environmental****Spills/Releases:**

Type of Spill: PRODUCED WATER

Estimated Spill Volume: 2

Comment: Operator reported "The operator reported a 1 inch valve at the Meter House had frozen and broke spilling produced water on the location. The operator isolated the leak upon discovery and is estimated at this time that 2bbls of produced water were spilled. All of the water remained on location around the Meter House with no State Waters involved."

Corrective Action: Operator shall provide root cause of spill and prevention procedures on Form 19 Subsequent within 10 days of spill as required per Rule 906.b

Date: 01/06/2018

Reportable: YES

GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water:

Depth to Ground Water:

**Water Well Complaint:**

Lat \_\_\_\_\_ Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
682600417	Inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4336551">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4336551</a>