

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401499537

Date Received:

01/02/2018

**FIR RESOLUTION FORM**

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

OGCC Operator Number: 10000

Name of Operator: BP AMERICA PRODUCTION COMPANY

Address: 380 AIRPORT RD

City: DURANGO State: CO Zip: 81303

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Beebe, Sabre

SanJuanCOGCC@bp.com

Sabre.Beebe@bp.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 680602246

Inspection Date: 11/08/2017

FIR Submit Date: 11/27/2017

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY

Company Number: 10000

Address: 380 AIRPORT RD

City: DURANGO State: CO Zip: 81303

LOCATION - Location ID: 325934

Location Name: WOMMER GAS UNIT A-N35N7W Number: 24NWSE County: LA PLATA

Qtrqtr: NWSE Sec: 24 Twp: 35N Range: 7W Meridian: N

Latitude: 37.283785 Longitude: -107.585834

FACILITY - API Number: 05-067- -00 Facility ID: 215589

Facility Name: WOMMER A Number: 1

Qtrqtr: NWSE Sec: 24 Twp: 35N Range: 7W Meridian: N

Latitude: 37.283785 Longitude: -107.585834

CORRECTIVE ACTIONS:

**1** CA# 112078

Corrective Action: Maintain roadside drainage and well pad BMPs to control stormwater erosion at the entrance to the access road and on the well pad as indicated. Additional stormwater controls are also needed to stabilize erosion.

Date: 12/30/2017

Response: CA COMPLETED

Date of Completion: 12/28/2017

Operator Comment: Armoring has been installed around the culvert drainage at entrance of location to ensure additional channeling is not continuing. Diversion ditches have been cleaned out and re-established and rock check dams installed to slow water velocity during storm events. Rock run down installed in erosion channel to armor against future

channelling. Please see attached photos of work completed.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment: Armoring has been installed around the culvert drainage at entrance of location to ensure additional channeling is not continuing. Diversion ditches have been cleaned out and re-established and rock check dams installed to slow water velocity during storm events. Rock run down installed in erosion channel to armor against future channelling. Please see attached photos of work completed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: \_\_\_\_\_

Title: Construction Specialist

Date: 1/2/2018 10:44:16 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

401499540	Work completed photos
-----------	-----------------------

Total Attach: 1 Files