

Photo#1:
Overview of Location from Entry to East.



December 20, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus KM Loc#423633

Photo#2:
Overview of Location to Northwest.



December 20, 2017



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus KM Loc#423633

Photo#3:

What appears to be open Rat Hole is positioned immediately South of Well API#045-20790, covered with square of light plastic grating.



Photo#4:



Photo#5:

Wattles at base of Fill Slope have become Debris .

Photo#6:



April 11, 2016

Inspection Photos: Chesapeake OP #103-07411